

**Cryptographic Products: The following products contain a polyurethane material that contains mercury:**

| Product                                                                      | System P                                     | System I                                                                                                                                                             | System Z                                                                                                                                                                                                      | OEM                                                                                 |
|------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| 4758-001<br>(Leeds1)<br>(no longer<br>orderable,<br>service only)            |                                              | <b>Feature Code 4800</b><br>FRU 10J0410 / PN 04K8979<br>FRU 09J8193 / PN 69H6617<br>FRU 10J0053 / PN 04K9403<br>FRU 10J0208 / PN 04K8905<br>FRU 10J0410 / PN 04K8979 |                                                                                                                                                                                                               | PN 04K9353<br>PN 40H9954<br>FRU 10J0688                                             |
| 4758-002<br>(Leeds 2)<br>(no longer<br>orderable,<br>service only)           | <b>Feature Code 4963</b><br>10J0357, 12R7869 |                                                                                                                                                                      | <b>TKE Feature</b> 0806, 0809, 0866, 0869,<br>0876, 0879, 0886, 0889, 0896 0899 ...<br>PN 40H9952 / FRU 10J0077<br>TKE 4.2 8141 ... 12R7867, 44P1608,<br>12R8074                                              | <b>FIPS4 3V</b> 10J0357<br><b>FIPS4 5V</b><br>04K9127, 04K9128,<br>10J0077, 12R7867 |
| 4764-01<br>(xCrypto)<br>(no longer<br>orderable,<br>service only)            |                                              | <b>Feature Code 4806</b><br>FRU 12R6540 / PN 12R6539<br>FRU 12R8246 / PN 12R8245                                                                                     | TKE 5.0 x206 0855 / 0859<br>12R8246<br>12R8566                                                                                                                                                                |                                                                                     |
| PCICC<br>Hydra 1.0<br>(no longer<br>orderable,<br>service only)              |                                              |                                                                                                                                                                      | <b>Feature Code 0860 (G5/G6)</b><br><u>Hydra / Leeds2</u><br>11P0303 40H9951<br>11P0869 40H9951                                                                                                               |                                                                                     |
| PCICC<br>Hydra 1.5<br>(no longer<br>orderable,<br>service only)              |                                              |                                                                                                                                                                      | <b>Feature Code 0861 (z900, z800)</b><br><u>Hydra / Leeds2</u><br>11P1004 40H9951<br>11P1925 40H9951<br>11P4398 40H9951                                                                                       |                                                                                     |
| PCIXCC<br>Hydra 1.75<br>(no longer<br>orderable,<br>service only)            |                                              |                                                                                                                                                                      | <b>Feature Code 0868 (z990, z890)</b><br><u>Hydra / xCrypto</u><br>60G7549 / 60G7520<br>16R0126 / 16R0962<br>12R6853 / 12R6759<br>12R7944 / 12R7875                                                           |                                                                                     |
| Crypto<br>Express2<br>Hydra 3.0<br>(no longer<br>orderable,<br>service only) |                                              |                                                                                                                                                                      | <b>Feature Code 0863 (z9 EC)</b><br><u>Hydra / xCrypto</u><br>12R6186 / 12R6539<br>12R7367 / 12R6539<br>12R7904 / 12R6539<br>12R8568 / 12R8245<br>12R9497 / 12R8245<br>12R9807 / 12R8245<br>12R9817 / 12R8565 |                                                                                     |